


21506320000

U. S. PUBLIC LAND SURVEY MONUMENT RECORD

SECTION 32 T 15 N, R 6 W, TOWN OF GREENFIELD

LA CROSSE COUNTY



LOCATION OF LANDMARK

WISCONSIN COORDINATE SYSTEM

North

East

Theta Angle

Horiz. Order

Vert. Order

TYPE OF LANDMARK 0.11' W. of corner is
 Berntsen ~~Top in exist. Iron Pipe.~~

BEARINGS ARE REFERENCED TO

Crew: WILLIAM C. JUNG
 PETER F. FOLLANSBEE
 Date: 5/12/1995

Crew: William C. Jung
 Peter F. Follansbee
 Date: 5/1/08

Describe any record evidence, monument evidence, testimonial evidence or any other material evidence you considered and whether the monument was found or restored through acceptance of an obliterated evidence location.

Curt Crook found this pipe at the corner in 1994. Apparently it had been set by a surveyor in Vernon County many years ago. Crook accepted this pipe as the best available evidence of the original government corner position. I agree. *****

Describe or show any material discrepancy between the location of the restored corner and that of the corner previously restored or reestablished.

None Known.

***** 5/1/08

The old marker and the sign and post were apparently washed out during a heavy rain. I set a 30" Berntsen marker in a large rock pile. The marker as set is 0.11 feet West of the actual corner. A sign and post were set to the East. The corner is on the East side of the washout.

5/1/08 Found all (4) B.T.'s w/PK's in.

RECORD OF DURABLE WITNESS MONUMENTS


NO	DESCRIPTION	MAGNETIC	DISTANCE
		BEARING	
1	Set P.K. Nail in NW-side 15" Oak	S 57° W	46.56 Ft.
2	Set P.K. Nail in NW-side 10" Basswood	S 54° W	23.57 Ft.
3	Set P.K. Nail in NW-side 3" Basswood	N 24° E	11.49 Ft.
4	Set P.K. Nail in E.-side 8" Basswood	S 05° W	38.33 Ft.

SE-Cor., Sec. 32-15-6.
Set a Berntsen Top in an existing Iron Pipe after it was plumbed up. Falls on the east side of a rocky washout. Buried a bottle containing a shell casing with the marker, mounded the pipe with rocks & set a sign & post on the east side

5/1/08
new a 30" Berntsen
in a large rock pile
0.11' West of the
actual corner.

(Not to scale)

(Note: distances are to P.K.
nails set in double blazed trees)



PLAN VIEW DRAWING OF REFERENCE TIES

MAP SHOWING DISTANCE AND DIRECTION TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR REESTABLISHING THE CORNER

This location was confirmed by Crook's measurements.

I, William C. Jung, County Surveyor
HEREBY CERTIFY THAT THE CORNER LOCATION SHOWN ON THIS RECORD
WAS DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND
THAT THIS U. S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT
AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

William C. Jung 8/17/95
Signature Date
Revised: 6/3/08
aweg

